

# SOFTWARE RELEASE NOTES



**Product:** Mbox Media Server  
**Manufacturer:** PRG  
**Subject:** Software Version 4.0.1  
**Bulletin No:** MBX-020  
**Date:** October 10, 2016



## INTRODUCTION

---

### Mbox Software Version 4.0.1

Software version 4.0.1 is now available for the Mbox Media Server applications including Mbox Designer, Mbox Studio, Mbox Mini, Mbox Director, and Mbox Remote.

### Overview

Software version 4.0.1 offers several notable bug fixes for issues in Mbox, Mbox Director, and Mbox Remote. A list of affected items can be found below.

#### Mbox:

- + Fix Output Master Shutter drawing origin
- + Fix issue affecting use of TC Reader stream when Audio input is set to “None” at launch
- + Add missing txfx file for Effect #188
- + UI fixes on Outputs/Mixes tabs when using dropdown menus
- + Fix crossfades on Layer Copy FX+ receivers
- + Fix issue with black flash when first applying an effect to an Output Master
- + Correct Multiscreen stride value interpretation
- + Fix sub-output vertical sizing when an effect is applied to that sub-output’s Output Master
- + Fix issue with crash upon releasing QC file
- + Allow multimodels to automatically reload when one of their component models is edited
- + Restore Strobe effect for use on Image Remapping screen objects
- + Fix issue with up/down direction for some effects in El Capitan (10.11.4+) and Sierra (10.12)
- + Fix issues relating to Image Units when frame blending is applied after a playspeed reduction
- + Fix issue when chaining some effects due to image size/center changing as effect values are modified
- + Fix for intermittent fullscreen flicker in Sierra
- + Fix HUD layer status values when using more than 19 layers

#### Director:

- + Fix OSC interactions with Output Masters
- + Fix issue with crash when Feedback All Layers is enabled and feedback is received
- + Add Effect #189 to profiles
- + Fix values for Global Master HUD/Macro popup
- + Fix crash on drag/drop to server

#### Remote:

- + Now uses localhost (127.0.0.1) when local IP Address is detected
- + Fix for Content Management thrashing on bad Ethernet connection
- + Correct vignette curve names and ordering

#### Multiscreen Editor:

- + Increase read frequency to allow faster loading of large configurations